Wor	·k O	rder	ID	5187	71

**B**1

Required Date: 9/14/2009

Page 1

Tuesday, September 08, 2009 12:40:06 PM

Item ID: Revision ID: D2235-1

Accept



Setup Start



Stop

Item Name: Start Date:

Basket Rib 9/9/2009

**Start Qty: 10.00** 

Req'd Qty: 10.00



**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Process Plan:

Date 09-9-08 Tooling:

Date:

Start Run

QC:

Date:\_\_\_\_\_

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID

Operation **Description**  Set Up/ **Run Hours**  Draw Number Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Insp. Number

Stamp

**Draw Nbr** 

**Revision Nbr** 

D2235

Rev B1

Memo

Memo

Large Fab

0.00

0.00

SAD 09-09-15 (10)

Large Fab Large Fab

100

1- Pick D3166-1 and cut as per dwg D2235 using DT8302□2- remove

identification markings on tube □3- deburr

110

QC

Quality Control

QC5- Inspect part completeness to step on W/O

Identify as per dwg & Stock Location: WA

120

0.00

SAD 69-09-17



Packaging

Packaging

Memo

0.00

## Work Order ID 51871

B1

Required Date: 9/14/2009

Page 2

Tuesday, September 08, 2009 12:40:06 PM

Item ID:

D2235-1

Accept

Setup Start



Stop

Item Name: **Start Date:** 

**Revision ID:** 

Basket Rib 9/9/2009

**Start Qty: 10.00** 

Operation

Description

Req'd Qty: 10.00

**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Process Plan:

Date: Date:

Tooling:

SPC (Y/N):

Date:

Date:

Start Run

Stop

Sequence ID/

Work Center ID

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**  Draw Number Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Number

Insp. Stamp

130

Quality Control

Memo

0.00

0.00

0969/18/9 - WF 09-18

## **Picklist Print**

Tuesday, September 08, 2009 12:40:12 PM

Work Order ID: 51871

Parent Item:

D2235-1RevB1

Parent Item Name: Basket Rib



Start Date: 9/9/2009

Required Date: 9/14/2009

**Start Qty: 10.00** 

Required Qty: 10.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date S	Status
D3166-1RevA1		Manufactured	No			100	Each	24.0000	10.0000			
I HERKIN THER HIRK HERD BILL BUILDER HER HER HER HER HER HER HER HER HER H								SAO	09-09-15			

Basket Hoop

Comments:

<u>Warehouse</u>	Loc Oty	Loc Code	
Location			
Main Warehouse			
WA	. 24		
51248	12	•	1
51474	12		_9

Page 1



DESIGN B WILLIAMS	DRAWN BY  B WILLIAMS	DART AEROSPACE VICTORIA INTERNATIONAL AIRPORT,			
CHECKED	APPROVED	DRAWING NO.		REV.	В
851	Bus	D2235	SHEET		
DATE		TITLE		SCA	<b>LE</b>
94:12:16		BASKET RIBS			

